

YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
				Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

DATE Sept 19, 2013 Engine TSO-896.0 Hobbs-326 Serial # 803266

Installed engine after repairs were made by Western Skyways inc. under work order P040141. Serviced cooling system IAW MM, bead system to release any trapped air. Installed IAW MM. Installed all new fluid carrying lines, oil, fuel, and water with hoses from PHT. Installed new engine air filter, new scat ducting, Installed new Ignition harness, routed wires and secured to prevent wear. Replaced on Spark plug on the number 5 cylinder pn-RHU32S. Replaced broken propeller deice brush at this time pn-RA211U-ROD. check good. Serviced engine with 13 quarts of aeroshell 100 Straight mineral oil at this time. Installed new cooling system thermostat, installed overhauled water cooling radiator and oil cooler at this time pn's 37.00068/2 and 37.00042/3. Installed new gaskets pn 640877 and pn 652456 on turbo mount flange at this time. Replaced turbo inlet duct pn-23504471. Torque all fluid carrying lines in engine compartment. Engine ground run and check was performed at this time IAW TCM TSIOL-550-C maintenance manual. All temps and pressures were all found to be within limits at this time. Leak check good at this time, engine was found safe for return to service at this time.

Ben Diaz
Ben Diaz A&P 609206270

Sep. 19, 2013 Engine TT - 896.0 hrs. Hobbs - 326.0 Serial No. 803266

This engine (Continental TSIOL-550C1B) has been inspected in accordance with an Annual Inspection and it was determined to be safe for service this date 09/19/13. Checked and found that all applicable ADs were previously complied with.

A. Domondon
A. Domondon, 1946639 IA

10-14-14 N65LL Tach-938.4 Hobbs-387 Engine entry

Drained engine oil, removed filter and cut open to inspect for debris, non found. Serviced with 13 quarts of aeroshell 100 50w. Inspected general security of wires, fluid carrying lines and ducts. check good. Inspected and checked gap on all spark plugs. Performed engine run up and leak check. check good.

Ben Diaz

Serial # 609206270